

**Addressing Subaru Vibration Issues****PROBLEM:**

*Subaru transmission mounts are susceptible to becoming very spongy and wear out due to the unique horizontal movement of a boxer (cylinders horizontally opposed engine. When these mounts wear, they cause the engine/transmission to sit slightly off center.*

**SOLUTION:** *Inspect and replace the transmission mount (if worn) to eliminate off center vibration issues. Note: if the mount is worn, the articulation angle of the new replacement axle becomes the mount that is holding the transmission in the correct location, which creates a binding vibration*

